











# Knoxville Bolt and Screw, Inc.

[www.knoxvillebolt.com](http://www.knoxvillebolt.com)

614 Sevier Avenue  
 P.O. Box 9149  
 Knoxville, TN 37920-1738

865-573-1991  
 800-231-3309  
 800-231-9566  
 FAX 865-573-8617

## Types of Screw Points

Type	Description	Use	Image
A	Tapping Screws Coarse threads and gimlet points.	Thin metal Resinous plywood Composite boards	
AB	Tapping Screws Spaced threads and gimlet points.	Thin metal Resinous plywood Composite boards	
B	Tapping Screws Spaced threads and blunt point with incomplete entering threads.	Thin metal Nonferrous castings Resinous plywood Plastics, and various Composite boards	
25 BT	Thread Cutting Screws Spaced, incomplete tapered threads, blunt point and tapered entering edges, with one or more cutting edges and chip removal indentations.	Plastic Asbestos Compositions Some composites	
F	Thread Cutting Screws Machine screw threads, blunt point, tapered entering edges, one or more cutting edges and chip removal indentations.	Nonferrous castings Steel sheets Plastics Brass Cast Iron, etc.	
23 T	Thread Cutting Screws Machine screw threads, blunt point, tapered entering edges, one or more cutting edges, chip removal indentations, and broad and deep cutting edge.	Nonferrous castings Steel sheets Plastics Brass Cast Iron, etc.	
17	Thread Cutting Screws Coarse tapping screw thread and special long sharp point fluted to capture chips.	Wood	
Tek 2 3	Self Drilling Screw Eliminates the need for drill bits or taps.	Automated assembly Thin sheet metal Heavier gauge metals	
U Drive	Round head metallic drive screws Multiple start threads with a pivot. Driven into undersized hole for great adherence. Round unslotted head.	Metals Plastics	